





STREET LIGHT POST SURVEY



- SENSOR MUST BE VERTICAL AND CONNECTED TO LAMP
- LENSES SHOULD BE PRESENT IN PROPER FRAME AND CLEAN
- LIGHT POST SHOULD BE PAINTED VERTICAL AND WITH OUT BENDS OR RUST
- ASSET ID NUMBER IS LOCATED ABOUT 8' FROM THE SW NUMBERED VERTICALLY. THIS NUMBER IS NOT ALWAYS PRESENT BUT IS ESSENTIAL TO RECORD IN SYSTEMATIC ORDER TO IDENTIFY LIGHTPOSTS IN SEQUENCE.
- BASE SHOULD BE PAINTED, VERTICAL AND WITHOUT RUST
- BASE COVER MUST BE IN PLACE EITHER ORIGINAL EQUIPMENT PREFERRED OR SUBSTITUTED WITH BANDING AND PLATE. IT IS A CODE VIOLATION TO ALLOW ACCESS TO THE WIRING AT THE BASE OF LIGHT POSTS. **HAZARD!**

DATE	TIME	LOCATION	SENSOR	LENS	POST	BASE	COVER	REMARKS
10/23	12:00	1000	1	1	1	1	1	1
10/23	12:00	1001	1	1	1	1	1	1
10/23	12:00	1002	1	1	1	1	1	1
10/23	12:00	1003	1	1	1	1	1	1
10/23	12:00	1004	1	1	1	1	1	1
10/23	12:00	1005	1	1	1	1	1	1
10/23	12:00	1006	1	1	1	1	1	1
10/23	12:00	1007	1	1	1	1	1	1
10/23	12:00	1008	1	1	1	1	1	1
10/23	12:00	1009	1	1	1	1	1	1
10/23	12:00	1010	1	1	1	1	1	1
10/23	12:00	1011	1	1	1	1	1	1
10/23	12:00	1012	1	1	1	1	1	1
10/23	12:00	1013	1	1	1	1	1	1
10/23	12:00	1014	1	1	1	1	1	1
10/23	12:00	1015	1	1	1	1	1	1
10/23	12:00	1016	1	1	1	1	1	1
10/23	12:00	1017	1	1	1	1	1	1
10/23	12:00	1018	1	1	1	1	1	1
10/23	12:00	1019	1	1	1	1	1	1
10/23	12:00	1020	1	1	1	1	1	1
10/23	12:00	1021	1	1	1	1	1	1
10/23	12:00	1022	1	1	1	1	1	1
10/23	12:00	1023	1	1	1	1	1	1
10/23	12:00	1024	1	1	1	1	1	1
10/23	12:00	1025	1	1	1	1	1	1
10/23	12:00	1026	1	1	1	1	1	1
10/23	12:00	1027	1	1	1	1	1	1
10/23	12:00	1028	1	1	1	1	1	1
10/23	12:00	1029	1	1	1	1	1	1
10/23	12:00	1030	1	1	1	1	1	1
10/23	12:00	1031	1	1	1	1	1	1
10/23	12:00	1032	1	1	1	1	1	1
10/23	12:00	1033	1	1	1	1	1	1
10/23	12:00	1034	1	1	1	1	1	1
10/23	12:00	1035	1	1	1	1	1	1
10/23	12:00	1036	1	1	1	1	1	1
10/23	12:00	1037	1	1	1	1	1	1
10/23	12:00	1038	1	1	1	1	1	1
10/23	12:00	1039	1	1	1	1	1	1
10/23	12:00	1040	1	1	1	1	1	1
10/23	12:00	1041	1	1	1	1	1	1
10/23	12:00	1042	1	1	1	1	1	1
10/23	12:00	1043	1	1	1	1	1	1
10/23	12:00	1044	1	1	1	1	1	1
10/23	12:00	1045	1	1	1	1	1	1
10/23	12:00	1046	1	1	1	1	1	1
10/23	12:00	1047	1	1	1	1	1	1
10/23	12:00	1048	1	1	1	1	1	1
10/23	12:00	1049	1	1	1	1	1	1
10/23	12:00	1050	1	1	1	1	1	1
10/23	12:00	1051	1	1	1	1	1	1
10/23	12:00	1052	1	1	1	1	1	1
10/23	12:00	1053	1	1	1	1	1	1
10/23	12:00	1054	1	1	1	1	1	1
10/23	12:00	1055	1	1	1	1	1	1
10/23	12:00	1056	1	1	1	1	1	1
10/23	12:00	1057	1	1	1	1	1	1
10/23	12:00	1058	1	1	1	1	1	1
10/23	12:00	1059	1	1	1	1	1	1
10/23	12:00	1060	1	1	1	1	1	1
10/23	12:00	1061	1	1	1	1	1	1
10/23	12:00	1062	1	1	1	1	1	1
10/23	12:00	1063	1	1	1	1	1	1
10/23	12:00	1064	1	1	1	1	1	1
10/23	12:00	1065	1	1	1	1	1	1
10/23	12:00	1066	1	1	1	1	1	1
10/23	12:00	1067	1	1	1	1	1	1
10/23	12:00	1068	1	1	1	1	1	1
10/23	12:00	1069	1	1	1	1	1	1
10/23	12:00	1070	1	1	1	1	1	1
10/23	12:00	1071	1	1	1	1	1	1
10/23	12:00	1072	1	1	1	1	1	1
10/23	12:00	1073	1	1	1	1	1	1
10/23	12:00	1074	1	1	1	1	1	1
10/23	12:00	1075	1	1	1	1	1	1
10/23	12:00	1076	1	1	1	1	1	1
10/23	12:00	1077	1	1	1	1	1	1
10/23	12:00	1078	1	1	1	1	1	1
10/23	12:00	1079	1	1	1	1	1	1
10/23	12:00	1080	1	1	1	1	1	1
10/23	12:00	1081	1	1	1	1	1	1
10/23	12:00	1082	1	1	1	1	1	1
10/23	12:00	1083	1	1	1	1	1	1
10/23	12:00	1084	1	1	1	1	1	1
10/23	12:00	1085	1	1	1	1	1	1
10/23	12:00	1086	1	1	1	1	1	1
10/23	12:00	1087	1	1	1	1	1	1
10/23	12:00	1088	1	1	1	1	1	1
10/23	12:00	1089	1	1	1	1	1	1
10/23	12:00	1090	1	1	1	1	1	1
10/23	12:00	1091	1	1	1	1	1	1
10/23	12:00	1092	1	1	1	1	1	1
10/23	12:00	1093	1	1	1	1	1	1
10/23	12:00	1094	1	1	1	1	1	1
10/23	12:00	1095	1	1	1	1	1	1
10/23	12:00	1096	1	1	1	1	1	1
10/23	12:00	1097	1	1	1	1	1	1
10/23	12:00	1098	1	1	1	1	1	1
10/23	12:00	1099	1	1	1	1	1	1
10/23	12:00	1100	1	1	1	1	1	1





HINTS
i PHONE - TURN OFF DATA.
To turn off your cellular data go to Settings > Mobile Data (or Cellular Data) and toggle the Mobile/Cellular Data switch to off. This will turn off all cellular data and restrict all data to Wi-Fi, including email, web browsing and push notifications

YOU WILL NEED TO TURN IT BACK ON LATER BUT WHILE YOU ARE ON THE STREET YOU DONT WANT TO USE UP ALL YOUR DATA AVAILABLE AND PAY EXTRA AT END OF MONTH.

TO TRANSFER DATA TO YOUR COMPUTER DO THE FOLLOWING
CONNECT YOUR IPHONE USING A USB CABLE TO YOUR PHONE.
YOU WILL NEED TO ALLOW ACCESS ON YOUR PHONE AND IT MAY TAKE A FEW TRYs.
A MENU SHOULD POP UP AND YOU NEED TO SELECT "TRANSFER PHOTOS" AND SELECT YOUR I PHONE AS THE SOURCE.
THEN SELECT ONLY THE PHOTOS YOU ARE TRANSFERING. YOU MAY NEED ONLY SELECT THE DATE. THEN CHECK THE "DELETE ORIGINAL ITEMS AFTER IMPORT". THEN "IMPORT FILES" SHOULD BE A BLUE BOX NEXT TO CANCEL. THE IMPORT WILL ILLUSTRATE THE FILE FOLDER THAT IT THE DESTINATION FOR THE FILES. IT SHOULD BE YOUR " PICTURE FOLDER". CHECK OK.

THEN GO TO THE PICTURE FOLDER AND REVEIW THE TRANSFER. IF IS THERE YOU ARE HALF WAY HOME. YOU CAN CLOSE THE PHOTO TRANSFER UTILITY BY CLICKING THE X.IN THE UPPER RIGHT HAND CORNER OF THE UTILITY

SELECT THE PHOTOS FOR THE STREET LIGHT PHOTOS ON EACH STREET AND PLACE THEM IN A FOLDER WITH THE SL SURV __NAME____, THEN SAVE THIS FOLDER TO "(YOUR NAME) LIGHTING SURV PHOTOS" FOLDER.
IF YOU ARE TAKEING STREET VIEW PHOTOS FOLLOW THE SAME PROCEDURE BUT THE FOLDER FOR THE SELECTED PHOTOS WILL BE THE STREET NAME ONLY.

ONCE YOU HAVE SAVED ALL THE PHOTOS TO THEIR FOLDER GO TO "GOOGLE DRIVE" AND DROP YOUR NAMED FOLDER TO THE DRIVE BY DRAG AND DROP. IF YOU ZIP THE FOLDERS IT WILL BE A QUICKER UP LOAD AND DOWN LOAD. AT LATER TIME WHEN YOU HAVE MORE FILES TO DOWN LOAD SIMPLY DOWNLOAD THE NEW STREET FOLDERS TO YOUR FOLDER ON THE GOOGLE DRIVE.

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

STREET		SURVEY				
LIGHT ID	STREET ADDRESS	STREETLIGHTS	LIGHT & LENS	FUNCTION	COVER	311 SUBMITTAL
from NOLA311		SURVEYED	DAMAGED OR CLEANING	NOT	REPAIR REPLACE	
26	RAMPART	22	2	2	1	0
58	BURGUNDY	58	29	11	15	10
57	DAUPHINE	57	30	13	16	12
61	BOURBON	61	47	14	14	9
1	ROYAL	73	47	17	26	16
74	CHARTERS	73	21	17	16	14
82	DECATUR	82	42	20	39	12
19	NORTH PETERS	19	7	0	4	0
4	EXCHANGE ALLY	4	1	2	1	3
4	DORSIERE STREET	4	0	1	4	0
4	CLINTON ALLY	4	1	0	3	0
22	FRENCH MARKET ST AND PLACE	22	4	2	6	0
34	CANAL STREET	28	23	13	11	8
36	IBERVILLE STREET	36	12	12	20	11
49	BIENVILLE STREET	38	10	9	23	9
47	CONTI STREET	33	8	12	15	12
27	ST LOUISE STREET	25	4	5	9	4
38	TOULOUSE STREET	29	5	5	10	5
8	WILKINSON AVE	8	6	1	2	1
42	ST PETERS STREET	39	16	3	9	3
24	ORLEANS STREET	16	2	2	3	2
42	ST ANN STREET	29	1	9	13	9
7	MADISON AVE	7	7	2	3	1
28	DUMAINE STREET	15	2	3	9	3
26	ST PHILLIPS STREET	14	0	1	7	1
30	URSULINES STREET	24	1	6	9	6
34	GOV NICHOLAS STREET	34	1	3	6	3
35	BARRACKS STREET	23	3	3	2	3
64	ESPLANADE	34	0	3	5	3
983	TOTAL LIGHTS	911	332	191	301	160
	PERCENTAGE NEEDING REPAIR		36%	21%	33%	

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

STREET BURGUNDY		SURVEY JORGENSEN 02012022								
LIGHT ID		CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
1300	BIH230	1316	OK	OK	YES					
	HP18	1303	OK	OK	YES					
	BIH229	X BARRACKS	OK	OK	NO					2022-858357
1200	HP17	CABRINNIE PK	OK	NEED CLEAN	YES					
	BIH228	CABRINNIE PK	MISSING	DAMAGED	NO				IMG-4134	2022-858358
	BJ2212	1225	OK	NEED CLEAN	YES	PAINT	PAINT			
1100	BIH227		OK	OK	YES					
	BJ8	1200	OK	NEED CLEAN	YES	PAINT	PAINT			
	AQ101	1141	OK	DAMAGED	YES	PAINT	PAINT		IMG-4138	
1000	BIH221	1132	OK	OK	NO					2022-858359
	AQ100	1123	OK	NEED CLEAN	YES	PAINT	PAINT		IMG-4139	
	AQ51	1106	OK	DAMAGED	YES				IMG-4140	
900	AQ99	1041	OK	DAMAGED	YES					
	AQ98	1021	OK	OK	YES					
	BIH220	1014	OK	OK	YES					
800	AQ97	1000	OK	NEED CLEAN	YES		PAINT	REPAIR UNSAFE	IMG-4143	NOT SUBMITTED
	AQ96	943	OK	OK	YES			HAZ MISSING		
	x	946	OK	OK	NO				IMG 4928	2022-863689
700	AQ95	921	OK	NEED CLEAN	YES			SUBSTITUTE		
	BIH218	916	OK	OK	YES					
	x	900	MISSING	MISSING	NO		REPAIR REPLACE	MISSING	IMG-4146	NOT SUBMITTED
600	AQ93	841	OK	OK	YES	PAY PHONE POST		SUBSTITUTE		
	BIH217	830	OK	OK	NO					2022-858361
	x	825	5G	TOWER	YES					
500	AQ91	800	OK	DAMAGED	YES			SUBSTITUTE		
	BIH	733	OK	OK	YES					
	x	731	OK	OK	YES					
400	AQ89	720	OK	DAMAGED	YES	BENT		SUBSTITUTE		
	AQ88	713	OK	NEED CLEAN	YES	PAINT				
	BIH212	710	OK	OK	YES					
300	AQ87	701	OK	DAMAGED	YES		PAINT			
	AQ86	638	OK	DAMAGED	YES	BENT	PAINT			
	AQ85	629	OK	NEED CLEAN	YES					
200	AQ84	616	OK	OK	YES					
	AQ83	601	OK	NEED CLEAN	YES	PAINT		SUBSTITUTE		
	x	540	5G	TOWER	YES					
100	AV150	527	OK	NEED CLEAN	YES					
	AV149	514	OK	NEED CLEAN	YES	PAINT	PAINT	HAZ MISSING		
	x	501	MISSING	MISSING	NO	MISSING	MISSING	HAZ MISSING		2022-858362
50	AV147	440 (940 ST LOUIS)	OK	NEED CLEAN	YES	PAINT	PAINT			
	AV146	435	OK	DAMAGED	YES	PAINT	PAINT			
	AV145	422	OK	DAMAGED	YES	PAINT	PAINT			
50	AV144	415	OK	DAMAGED	YES	PAINT				
	AV143	410	OK	OK	ON 24	PAINT	PAINT			2022-858363
	AV142	401 (1003 CONTI)	OK	OK	YES			SUBSTITUTE		
50	x	AT CONTI	5G	TOWER	YES					
	AV140	333	OK	OK	YES					
	AV139	324	OK	CLEAN	YES			SUBSTITUTE		
50	AV138	317	OK	OK	YES	PAINT	PAINT	HAZ MISSING		
	AV137	308	OK	OK	YES					
	x	301	5G	TOWER	NO					NOT SUBMITTED
50	AV	240	OK	DAMAGED	YES	PAINT	PAINT			
	x	231	5G	TOWER	YES					
	AV133	240	ON	DAMAGED	YES	REPAIR AND PAINT	PAINT			
50	AV132	231	MISSING	MISSING	NO	PAINT	PAINT	SUBSTITUTE		2022-858366
	x	200	5G	TOWER	YES					
	AV129	129	OK	NEED CLEAN	NO	PAINT	PAINT	SUBSTITUTE		2022-858371
50	AV127	129	DAMAGED	OK	NO			SUBSTITUTE		2022-858371

58	58	5	29	11			15		10				
			50%	19%			26%						
	MISSING	4	3	0			1						
	DAMAGED	1	13	0			0						
	NO	0	0	11			0						
	SUBSTITUTE	0	0	0			10						
	HAZ MISSING	0	0	0			4						
	NEED CLEAN	0	13	0			0						

DAUPHINE STREET		SURVEY JORGENSEN 02032022							
LIGHT ID (1)	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
HP14	1323	OK	OK	NO	OK	OK	OK		2022-860166
BJ 1	1300	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG- 4273	
x	CABRINI 1241	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG- 4274	
x	1231	OK	OK		OK	OK	OK	IMG- 4275	
BJ 3	1221	OK	NEED CLEAN		OK	OK	OK		
x	1220	OK	OK	NO	OK	OK	OK	IMG- 4276	2022-860161
BJ 4	1200	OK	NEED CLEAN		NEED PAINT	NEED PAINT	SUBSTITUTE	IMG- 4277	
BJ 5	1139	OK	NEED CLEAN		NEED PAINT	NEED PAINT	HAZ MISSING	IMG- 4278	
BJ 6	1119	OK	NEED CLEAN		NEED PAINT	NEED PAINT	OK	IMG- 4279	
BIH 126	1115	OK	OK	NO	OK	OK	OK	IMG- 4280	2022-860159
BJ 7	1104	OK	NEED CLEAN		OK	OK	OK	IMG- 4281	
AQ48	1043	OK	OK	NO	OK	OK	OK	IMG- 4282	2022-860157
BIH 224	1035	OK	DAMAGED	NO	OK	OK	OK	IMG- 4283	2022-860153
x	1021			5G				IMG- 4284	
AQ 60	1000	OK	NEED CLEAN		OK	OK	OK	IMG- 4285	
AV 60	941	OK	NEED CLEAN		NEED PAINT	NEED PAINT	OK		
x	927	OK	DAMAGED		OK	OK	OK	IMG- 4287	
AQ 63	904	OK	OK		OK	OK	OK	IMG- 4288	
AQ 64	841 (900 DUMAIN)	OK	OK		OK	OK	OK	IMG- 4289	
AQ 65	825	DAMAGED	OK		OK	OK	OK	IMG- 4290	
BIH 215	814	OK	OK	NO	OK	OK	OK	IMG- 4291	2022-860149
x	800 (839 ST ANN)	OK	NEED CLEAN		NEED PAINT	NEED PAINT	SUBSTITUTE	IMG-4292	
AQ 67	737	OK	OK		OK	OK	OK		
AQ 68	726	OK	OK		NEED PAINT	NEED PAINT	OK	IMG-4293	
AQ 69	715	OK	OK	NO	OK	OK	OK		2022-859670
BIH 211	716	OK	OK		OK	OK	OK	IMG-4295	
x	701	OK	NEED CLEAN		NEED PAINT	NEED PAINT	OK	IMG-4298	
x	642			5G				IMG-4299	
AQ 72	625	OK	NEED CLEAN		NEED PAINT	NEED PAINT	OK		
BIH 210	622	OK	OK	NO	OK	OK	OK	IMG-4301	2022-859669
AV 151	612	OK	NEED CLEAN		OK	OK	OK		
AV 152	601 (901 TOULOUSE)	OK	OK	NO	OK	OK	OK	IMG-4302	2022-859666
x	534	MISSING	MISSING	NO	xxxxxxxx	xxxxxxxx	MISSING	IMG-4303	
AV 154	527	OK	OK		OK	OK	OK	IMG-4304	
AV 155	512	OK	NEED CLEAN		OK	OK	OK	IMG-4305	
AV156	501	DAMAGED	NEED CLEAN		OK	OK	SUBSTITUTE	IMG-4308	
AV 157	438	OK	DAMAGED		OK	OK	OK	IMG-4309	
AV 158	431	OK	DAMAGED		NEED PAINT	NEED PAINT	HAZ MISSING	IMG-4310	
AV 159	430	OK	NEED CLEAN		OK	OK	OK	IMG-4312	
AV 160	415	OK	OK		OK	OK	SUBSTITUTE	IMG-4313	
AV 161	400	OK	NEED CLEAN	5G	OK	OK	OK	IMG-4314	
AV 163	340 (846 CONTI)	OK	OK	MAISON DUPUY PLATE AFFIXED	OK	OK	OK	IMG-4316	
AV 164	335	OK	OK		OK	OK	SUBSTITUTE	IMG-4317	
AV 165	320	OK	NEED CLEAN		OK	OK	SUBSTITUTE		
AV1 166	323	OK	OK		OK	OK	OK	IMG-4320	
AV 167	306	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG-4321	
x	241	MISSING	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG-4322	2022-859658
AV 169	240	MISSING	MISSING	NO	OK	OK	OK	IMG-4323	2022-859662
AV 170	234	MISSING	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG-4324	2022-859664
AV 171	240	OK	OK		OK	OK	OK	IMG-4325	
AV 172	215	OK	OK		OK	OK	OK	IMG-4326	
AV 173	200	OK	DAMAGED		OK	OK	HAZ MISSING	IMG-4327	
AV 174	201	OK	OK		OK	OK	OK	IMG-4328	
AV 175	140	OK	OK		OK	OK	OK		
AV 176	137	DAMAGED	DAMAGED		OK	OK	OK	IMG-4330	
AV 178	135	OK	NEED CLEAN		RESET PLUMB	RESET PLUMB	SUBSTITUTE	IMG-4331	
AV 179	100	OK	OK		OK	OK	OK		

57	57	7	30	13			16		12
			53%	23%			28%		
	MISSING	4	2	0			1		
	DAMAGED	3	8	0			0		
	NO	0	0	13			0		
	SUBSTITUTE	0	0	0			12		
	HAZ MISSING	0	0	0			3		
	NEED CLEAN	0	20	0			0		

STREET BOURBON		SURVEY JORGENSEN 02042022									
LIGHT ID		CLOSEST ADDRESS		SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
1300	x		1311	OK	OK		OK	OK	OK		
	x		1350	OK	NEED CLEAN		OK	OK	OK		
	BJ 94		1303	OK	OK		OK	OK	OK	IMG-4364	
	BJ 93		1250	OK	OK		OK	OK	OK	IMG 4365	
	BJ 92		1229	OK	NEED CLEAN		OK	OK	OK	IMG 4366	
1200	BIH 236		1228	OK	OK	NO	OK	OK	OK	IMG 4367	2022-859597
	BJ 91		1225	OK	NEED CLEAN		OK	OK	OK	IMG 4368	
	BJ 90		1209	OK	NEED CLEAN		OK	OK	OK	IMG 4369	
	BJ 89		1200	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4370	
	BJ 88		1139	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4371	
1100	BJ 87		1132	OK	NEED CLEAN		NEED PAINT	OK	OK	IMG 4372	
	BJ 86		1119	OK	OK		NEED PAINT	OK	OK	IMG 4373	
	BJ 85		1112	OK	OK		OK	OK	HAZ MISSING	IMG 4374	
	BJ 84		1105	OK	OK		OK	OK	OK	IMG 4375	
	BJ 83		1100	OK	OK		OK	OK	OK	IMG 4376	
1000	BJ 81		1032	OK	NEED CLEAN		OK	OK	OK	IMG 4377	
	BJ 80		1029	OK	NEED CLEAN		OK	OK	OK	IMG 4378	
	BJ 79		1014	OK	NEED CLEAN		OK	OK	OK	IMG 4379	
	BJ 78		1000	OK	NEED CLEAN		OK	OK	OK	IMG 4380	
	x		941	OK	NEED CLEAN		OK	OK	OK	IMG 4381	
900	BJ 76		932	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4382	
	x		923			5G				IMG 4383	
	AQ 45		907	DAMAGED	NEED CLEAN		OK	OK	OK	IMG 4384	
	x		841	OK		0	OK	OK	OK	IMG 4385	
	AQ 45		834	OK	OK	NO	OK	OK	OK	IMG 4388	2022-859602
800	AQ 41		819	OK	OK		OK	OK	OK	IMG 4389	
	AQ 40		818	OK	NEED CLEAN		OK	OK	OK	IMG 4390	
	x		811			5G				IMG 4391	
	AQ 43		800	OK	NEED CLEAN	NO	OK	OK	SUBSTITUTE	IMG 4392	2022-859610
	x		741	DAMAGED	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG 4393	2022-859613
700	AQ 36		733	OK	OK		PAY PHONE	OK	SUBSTITUTE		
	x	720 (BURBON @ ORLEANS		OK	OK		OK	OK	OK	IMG 4394 / 4395	
	x		717	OK	OK		OK	NEED PAINT	SUBSTITUTE	IMG 4396	
	x		701	OK	OK		OK	OK	SUBSTITUTE	IMG 4397	
	x		640	OK	DAMAGED		OK	OK	OK	IMG 4398	
600	x		627	OK	OK		OK	OK	OK	IMG 4399	
	AV 249		614	OK	OK		OK	OK	OK	IMG 4400	
	AV 248		601	OK	OK	5G	OK	OK	OK	IMG 4401	
	AV 247		540	OK	NEED CLEAN		OK	OK	OK	IMG 4402	
	AV 246		531	OK	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG 4403	2022-859620
500	AV 245		516	OK	DAMAGED		OK	OK	OK	IMG 4404	
	ZX 88		501	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4405	
	AV 239		435	OK	OK	NO	OK	OK	OK	IMG 4406	2022-859622
	AV 241		424	OK	OK	NO	OK	OK	OK	IMG 4407	2022-859624
	AV 240		417	DAMAGED	OK	NO	OK	OK	OK	IMG 4408	2022-859633
400	x		400	DAMAGED	DAMAGED	NO	OK	OK	OK	IMG 4409	2022-859629
	AV 228		401	OK	NEED CLEAN		OK	OK	OK	IMG 4410	
	AV 227		340	DAMAGED	OK		OK	OK	OK	IMG 4411	
	x		333	DAMAGED	NEED CLEAN		OK	OK	OK	IMG 4412	
	AV234		330	OK	NEED CLEAN	NO	OK	OK	OK	IMG 4413	
300	x		327	OK	OK		OK	OK	OK	IMG 4414	
	AV 232		320	OK	DAMAGED		OK	OK	OK	IMG 4415	
	x		301	OK	DAMAGED		OK	OK	OK		
	x		240	MISSING	DAMAGED		OK	OK	OK		
	x		235	OK	DAMAGED		OK	OK	SUBSTITUTE	IMG 4418	
200	AV 228		222	OK	NEED CLEAN		OK	OK	OK	IMG 4419	
	AV 227		212	OK	NEED CLEAN		OK	OK	OK		
	AV 223		117	NOT VISIBLE	OK	NO	OK	OK	SUBSTITUTE	IMG 4427	2022-859638
	BOU 100		110	NOT VISIBLE	OK	NO	OK	OK	OK	IMG 4429	2022-859650
	AV 228		111	NOT VISIBLE	OK	NO	OK	OK	HAZ MISSING	IMG 4431	2022-859652
100	x		100	NOT VISIBLE	OK	NO	OK	OK	OK	IMG 4433	2022-859656

61	61	7	32	14			14		9
			52%	23%			23%		
	MISSING	1	0	0			0		
	DAMAGED	6	9	0			0		
	NO	0	0	14			0		
	SUBSTITUTE	0	0	0			12		
	HAZ MISSING	0	0	0			2		
	NEED CLEAN	0	23	0			0		

TOTALS	61	13	35	14	2	2	2	13
		12%	32%	13%	2%	2%	2%	

	STREET	ROYAL	SURVEY JORGENSEN 02062022		LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
			CLOSEST ADDRESS	SENSOR							
1300			1330	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4462	
			1315	OK	NEED CLEAN		OK	PAINT	OK	IMG 4463	
			1306	OK	OK		OK	OK	OK	IMG 4464	
			1241	OK	NEED CLEAN		OK	OK	OK	IMG 4465	
			1230	OK	NEED CLEAN		PAINT	PAINT	OK	IMG 4466	
1200			1223	OK	OK		OK	OK	OK	IMG 4467	
			1214	OK	NEED CLEAN		OK	OK	OK	IMG 4468	
			1211	OK	DAMAGED		OK	OK	OK	IMG 4469	
			1200			5G				IMG 4470	
			1139	OK	DAMAGED	NO	PAINT	PAINT	HAZ MISSING	IMG 4471	2022-886188
1100			1134	OK	NEED CLEAN	NO	OK	OK	SUBSTITUTE	IMG 4472	2022-886195
			1125	OK	DAMAGED		OK	OK	SUBSTITUTE	IMG 4473	
			1116	OK	NEED CLEAN		OK	OK	OK	IMG 4474	
			1109	OK	NEED CLEAN		OK	PAINT	OK	IMG 4475	
			1100	OK	OK		OK	OK	SUBSTITUTE	IMG 4476	
1000			1041	OK	OK	TEL	OK	OK	SUBSTITUTE	IMG 4477	
			1026	OK	OK		OK	OK	SUBSTITUTE	IMG 4478	
			1023	OK	OK	5G	OK	OK	HAZ MISSING	IMG 4479	
			1012	OK	NEED CLEAN		OK	OK	OK	IMG 4480	
			1001	OK	NEED CLEAN		PAINT	PAINT	OK	IMG 4481	
900			1000	OK	NEED CLEAN	NO	OK	PAINT	SUBSTITUTE	IMG 4482	2022-886197
			941	OK	OK		OK	OK	SUBSTITUTE	IMG 4483	
			934	OK	NEED CLEAN		OK	OK	OK	IMG 4484	
			919	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4485	
			912	OK	DAMAGED		OK	OK	OK	IMG 4486	
800			905	OK	OK	NO	OK	OK	OK	IMG 4487	2022-886198
			900	DAMAGED	OK	NO	OK	OK	SUBSTITUTE	IMG 4488	2022-886200
			837	OK	NEED CLEAN	NO	PAINT	PAINT	OK	IMG 4489	2022-886202
			830	OK	NEED CLEAN		OK	OK	OK	IMG 4490	
			821	OK	NEED CLEAN	NO	OK	OK	OK	IMG 4491	2022-886204
700			814	OK	NEED CLEAN		OK	OK	OK	IMG 4492	
			805	OK	OK		OK	OK	OK	IMG 4493	
			800	OK	DAMAGED	NO	OK	OK	OK	IMG 4494	2022-886205
			737	OK	NEED CLEAN		OK	OK	OK	IMG 4495	
			733	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4496	
600			730	OK	NEED CLEAN		PAINT	PAINT	SUBSTITUTE	IMG 4497	
			717	OK	OK		OK	OK	OK	IMG 4498	
		7'12	703	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4499	
			703	OK	NEED CLEAN		OK	PAINT	HAZ MISSING	IMG 4500	
			640	DAMAGED	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG 4501	2022-886206
500			630	OK	NEED CLEAN	NO	OK	OK	SUBSTITUTE	IMG 4503	2022-886209
			629	MISSING	MISSING	NO	OK	PAINT	OK	IMG 4504	2022-886210
			612	OK	NEED CLEAN		OK	OK	OK	IMG 4505	
			611	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4506	
			601	OK	OK		OK	OK	SUBSTITUTE	IMG 4507	
400			541	OK	OK		OK	OK	OK		
			540	OK	NEED CLEAN		OK	OK	OK	IMG 4508	
			533	OK	NEED CLEAN	NO	OK	PAINT	SUBSTITUTE	IMG 4509	2022-886211
			532	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4510	
			519	OK	NEED CLEAN		OK	PAINT	OK	IMG 4511	
300			514			5G				IMG 4512	
			501	MISSING	NEED CLEAN	NO	PAINT	PAINT	SUBSTITUTE	IMG 4513	2022-886218
			440	OK	DAMAGED	NO	OK	OK	OK	IMG 4514	2022-886220
			433	OK	NEED CLEAN		OK	OK	OK	IMG 4515	
			428	DAMAGED	OK		OK	OK	OK	IMG 4516	
200			417	DAMAGED	DAMAGED	NO	OK	OK	OK	IMG 4517	2022-886221
			408	OK	DAMAGED		PAINT	PAINT	SUBSTITUTE	IMG 4518	
			401	OK	DAMAGED		OK	OK	OK	IMG 4519	
			340	OK	NEED CLEAN		OK	OK	OK	IMG 4520	
			333	OK	NEED CLEAN	NO	OK	REPAIR ELE SOCKET	OK	IMG 4521	2022-886224
100			324	OK	NEED CLEAN		OK	OK	OK	IMG 4522	
			301	OK	NEED CLEAN		OK	PAINT	OK	IMG 4523	
			240	OK	DAMAGED		OK	OK	OK	IMG 4524	
			233	OK	OK		OK	OK	OK	IMG 4525	
			226			5G				IMG 4526	
			217	OK	OK		OK	OK	OK		
			200	OK	OK		OK	OK	OK	IMG 4527	
			201	OK	OK		OK	OK	SUBSTITUTE		
			134	OK	OK		OK	OK	OK	IMG 4528	
			131	OK	OK		OK	OK	OK	IMG 4529	
			121	OK	OK	NO	OK	OK	HAZ MISSING	IMG 4530 / 4531	2022-886226
			106	OK	OK		OK	OK	OK	IMG 4532	
			101	OK	OK		OK	OK	OK	IMG 4533	

1	73	6	47	17	26	16
			64%	23%	36%	
MISSING		2	1	0	0	
DAMAGED		4	11	0	0	
NO		0	0	17	0	
SUBSTITUTE		0	0	0	22	
HAZ MISSING		0	0	0	4	
NEED CLEAN		0	35	0	0	

CHARTERS STREET		JORGENSEN SURVEY 02092022							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
PR541	108	OK	DAMAGED		OK	OK	OK	IMG 4593	2022-886386
PR542	115	OK	OK		OK	OK	OK	IMG 4594	
PR543	108	OK	OK		OK	OK	SUBSTITUTE	IMG 4595	
PR544	129	OK	CLEAN		PAINT	PAINT	OK	IMG 4596	
AV262	130			5G				IMG 4597	
AV263	210	DAMAGED	DAMAGED	NO	OK	OK	OK	IMG 4598	2022-886389
AV264	217	OK	CLEAN		OK	OK	SUBSTITUTE	IMG 4599	
AV265	224	DAMAGED	DAMAGED	NO	OK	OK	OK	IMG 4600	2022-886392
AV266	233	OK	CLEAN		OK	OK	OK	IMG 4601	
AV267	240			NO				IMG 4602	2022-886399
AV26	301	OK	CLEAN		OK	OK	OK	IMG 4604	
AV269	306	OK	CLEAN		OK	OK	OK		
AV270	315	OK	CLEAN		OK	OK	OK	IMG 4605	
AV271	328	OK	CLEAN		OK	PAINT	OK	IMG 4606	
AV272	335	OK	CLEAN		OK	OK	SUBSTITUTE	IMG 4607	
AV405	340	OK	OK		OK	OK	OK	IMG 4608	
AV273	401	OK	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG 4610	2022-886401
AV274	410	OK	OK	NO	OK	OK	OK	IMG 4611	
AV275	401	OK	CLEAN	NO	OK	OK	OK	IMG 4612	2022-886407
AV276	422	OK	CLEAN	5G	PAINT	OK	SUBSTITUTE	IMG 4613	
BIH207	439	OK	OK	NO	OK	OK	OK	IMG 4614	2022-886409
AV278	440	OK	CLEAN		PAINT	PAINT	OK	IMG 4615	
AV279	519	OK	CLEAN	NO	OK	OK	OK	IMG 4616	2022-886415
AV280	519	OK	OK	NO	OK	OK	OK	IMG 4617	
x	516	OK	OK		OK	OK	OK	IMG 4618	
AV281	501			5G				IMG 4619	
BIH209	534	OK	OK	NO	OK	OK	OK	IMG 4620	2022-886426
AV282	536	DAMAGED	OK		OK	OK	OK	IMG 4621	
AV283	600	OK	CLEAN		OK	PAINT	SUBSTITUTE		
AV284	601	DAMAGED	DAMAGED		OK	PAINT	SUBSTITUTE	IMG 4622	
AV286	616	OK	OK		OK	OK	OK		
AV285	617	OK	CLEAN		OK	OK	OK	IMG 4623	
AV287	629	OK	OK	NO	OK	OK	OK	IMG 4624	2022-886436
BN496	630	COVER	COVER		OK	OK	OK	IMG 4625	
AV288	701	COVER	COVER		OK	OK	SUBSTITUTE	IMG 4628	
AB4	703	COVER	COVER		OK	OK	SUBSTITUTE	IMG 4629	
AB	705	COVER	COVER		OK	OK	OK	IMG 4630	
x	707	COVER	COVER		OK	OK	OK	IMG 4631	
x	709	COVER	COVER		OK	OK	OK	IMG 4632	
AE45	711	OK	DAMAGED		OK	OK	HAZ MISSING	IMG 4633	
AE42	713	OK	DAMAGED		OK	OK	OK	IMG 4634	
MOBILE	715	OK	OK	4 EACH	OK	OK	OK	IMG 4635	
43	739	DAMAGED	DAMAGED		OK	OK	SUBSTITUTE	IMG 4636	
AE49	800	COVER	COVER	TELE OUT	OK	OK	SUBSTITUTE	IMG 4637	2022-886442
VA 485	810	OK	CLEAN		OK	OK	OK	IMG 4638	
AE48	817	OK	NEED CLEAN		OK	OK	OK	IMG 4639	
BIH249	818	OK	OK		OK	OK	OK		
AE55	822	OK	DAMAGED		OK	OK	OK		
ZX116	828	OK	NEED CLEAN		OK	OK	OK	IMG 4640	
BJ127	839	DAMAGED	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4641	
BJ128	900	OK	DAMAGED		OK	OK	OK	IMG 4642	
BIH241	911	OK	OK		OK	OK	OK	IMG 4643	
x	915			5G					
BIH242	920	OK	OK		OK	OK	OK	IMG 4644	
x	921	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4645	
BJ130	940	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4646	
BJ131	1001	OK	OK		OK	OK	OK	IMG 4647	
BJ132	1023	OK	NEED CLEAN		OK	OK	OK	IMG 4648	
BIH244	1030	OK	OK	NO	OK	OK	OK	IMG 4649	2022-886446
x	1039			5G				IMG 4650	
BJ134	1100	OK	OK	NO	OK	OK	OK	IMG 4651	2022-886451
BJ135	1112	DAMAGED	DAMAGED	NO	DAMAGED	OK	SUBSTITUTE	IMG 4653	
BJ136	1119	OK	NEED CLEAN		OK	OK	OK	IMG 4654	
BJ137	1116	OK	OK		PAINT	PAINT	OK	IMG 4655	
BIH245	1138	OK	OK	NO	OK	OK	OK	IMG 4656	2022-886455
BJ138	1139	OK	OK		OK	OK	OK	IMG 4657	
BJ139	1200	OK	NEED CLEAN		OK	OK	OK	IMG 4658	
x	1201			5G				IMG 4659	
BIH246	1226	OK	OK	NO	OK	OK	OK	IMG 4660	2022-886458
BJ141	1239	OK	NEED CLEAN		PAINT	OK	OK	IMG 4661	
BJ142	1300	OK	NEED CLEAN		OK	OK	OK	IMG 4662	2022-886462
x	1301	OK	OK		OK	OK	OK		
BIH248	1318	OK	OK	NO	OK	OK	OK	IMG 4663	2022-886460

74	73	7	21	17			16		14
			29%	23%			22%		
	MISSING	0	0	0			0		
	DAMAGED	7	11	0			0		
	NO	0	0	17			0		
	SUBSTITUTE	0	0	0			15		
	HAZ MISSING	0	0	0			1		
	NEED CLEAN	0	10	0			0		

DECATUR STREET		SURVEY JORGENSEN 02102022								
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL	
PR530	100	OK	OK	NO	OK	OK	SUBSTITUTE	IMG4728	2022-886956	
PR531	113	OK	OK		OK	OK	OK	IMG4729		
PR532	100	OK	OK		OK	OK	SUBSTITUTE	IMG4730		
PR533	131	OK	DAMAGED		OK	OK	OK	IMG4731		
PR534	100	OK	NEED CLEAN		OK	OK	OK	IMG4732		
PR535	201	DAMAGED	DAMAGED		PAINT	OK	HAZ MISSING	IMG4733		
PR536	206	OK	NEED CLEAN		OK	OK	OK	IMG4734		
PR537	225	OK	OK		OK	OK	OK	IMG4735		
PR538	226	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG4736		
x	235	OK	NEED CLEAN		PAINT	PAINT	HAZ MISSING	IMG4737		
AV336	240	DAMAGED	NEED CLEAN		OK	OK	OK	IMG4738	2022-886961	
AV335	301	OK	OK		OK	OK	OK	IMG4739		
AV334	300	OK	NEED CLEAN		OK	OK	OK	IMG4740		
AV333	315	OK	OK		OK	OK	OK	IMG4741		
AV332	330	OK	NEED CLEAN		OK	OK	OK	IMG4742		
AV331	331	OK	OK		OK	OK	SUBSTITUTE	IMG4743		
AV329	407	OK	OK	NO	OK	OK	SUBSTITUTE	IMG4744		
BIH204	405 X	OK	OK		OK	OK	OK	IMG4745		
AV327	411	OK	OK	NO	OK	OK	OK	IMG4746		
BIH206	425X	OK	OK		OK	OK	OK	IMG4747		
AV326	425	OK	NEED CLEAN	NO	OK	OK	OK	IMG4748	2022-886963	
AV325	439	OK	NEED CLEAN	2	OK	OK	OK	IMG4749		
AV449	439X	OK	OK	NO	OK	OK	OK	IMG4750		
AV450	500	OK	OK	2	PAINT	OK	SUBSTITUTE	IMG4751		
AV451	500	OK	OK	2	PAINT	PAINT	HAZ MISSING	IMG4752		
AV323	515	OK	NEED CLEAN	2	OK	OK	SUBSTITUTE	IMG4753		
AE117	500	OK	OK	2	OK	OK	SUBSTITUTE	IMG4754		
x	531	OK	OK	2	OK	OK	SUBSTITUTE	IMG4755		
AV30	535	OK	OK	NO	OK	OK	OK	IMG4756		
AV2	500	OK	OK	2	PAINT	OK	SUBSTITUTE	IMG4757		2022-886967
AE33	601	OK	OK		OK	OK	SUBSTITUTE	IMG4758		
AE3	600	OK	OK		OK	OK	HAZ MISSING	IMG4759		
UA377	600	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG4760		
UA378	615	OK	OK		OK	OK	SUBSTITUTE	IMG4761		
AE34	620	DAMAGED	NEED CLEAN	NO	OK	OK	OK	IMG4762		
AE35	620	OK	OK		OK	OK	OK	IMG4763		
AE36	620	OK	OK		PAINT	PAINT	OK	IMG4764		
AE27	633	OK	DAMAGED		OK	OK	OK	IMG4765		
AE8	700	OK	NEED CLEAN	NO	OK	OK	HAZ MISSING	IMG4766	2022-886970	
AE26	700	DAMAGED	OK	5G	OK	OK	J	IMG4767		
AE24	700	OK	DAMAGED	NO	OK	PAINT	OK	IMG4768		
AE38	701	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG4769		
AE2	701	OK	DAMAGED		PAINT	PAINT	OK	IMG4770		
AE53	701	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG4771		
AE23	700	OK	OK	NO	DAMAGED	DAMAGED	SUBSTITUTE	IMG4772		
x	700	OK	DAMAGED		OK	OK	OK	IMG4773		
AE21	700	OK	OK		OK	OK	SUBSTITUTE	IMG4774		
UA383	801	OK	OK		OK	OK	SUBSTITUTE	IMG4775		2022-886971
AE52	811	OK	DAMAGED		OK	OK	SUBSTITUTE	IMG4776		
UA384 (2484)	825	OK	NEED CLEAN	NO	OK	OK	OK	IMG4777		
UA383	827	OK	DAMAGED		OK	OK	SUBSTITUTE	IMG4778		
AE59	840	OK	OK		OK	OK	SUBSTITUTE	IMG4779		
AE58	901	OK	NEED CLEAN		OK	OK	HAZ MISSING	IMG4780		
BI185	913	DAMAGED	DAMAGED	NO	PAINT	OK	OK	IMG4781		
AE65	912	OK	NEED CLEAN		OK	OK	OK	IMG4782		
AE17	912 MEDIAN	OK	OK		OK	OK	OK	IMG4783		
AE60	930	OK	OK		OK	OK	SUBSTITUTE	IMG4784	2022-886980	
BU 93	930 MEDIAN	DAMAGED	DAMAGED		OK	OK	OK	IMG4785		
BI194	933 MEDIAN	OK	NEED CLEAN	NO	OK	OK	OK	IMG4786		
BI183	941	OK	OK		OK	OK	SUBSTITUTE	IMG4787		
BI196(1867)	1000	OK	NEED CLEAN	NO	OK	OK	OK	IMG4787		
BI182	1005	OK	NEED CLEAN	NO				IMG4788		
BI197	1000	OK	DAMAGED		OK	OK	SUBSTITUTE	IMG4789		
x	1019	OK	OK		OK	OK	SUBSTITUTE	IMG4790		
BI198	1020	OK	NEED CLEAN		OK	OK	OK	IMG4791		
x	1039			5G				IMG4792		2022-887070
BI200	1040	OK	NEED CLEAN		OK	OK	HAZ MISSING	IMG4793		
BI179	1100		DAMAGED	NO				IMG4794		
BI178	1107	OK	DAMAGED		OK	OK	SUBSTITUTE	IMG4795		
BI176	1122	OK	NEED CLEAN	NO	OK	OK	OK	IMG4797		
BI177	1125	OK	DAMAGED	NO	OK	OK	HAZ MISSING	IMG4798		
BI175	1136	OK	OK		OK	OK	SUBSTITUTE	IMG4799		
x	1141			5G				IMG4800		
BI173	1200	DAMAGED	OK		OK	OK	SUBSTITUTE	IMG4801		
BI172	1207	OK	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG4802	2022-887073	
A 7	1218	OK	DAMAGED		OK	OK	OK	IMG4803		
BI171	1225	OK	NEED CLEAN		OK	OK	OK	IMG4804		
AU266	1234	OK	OK		OK	OK	OK	IMG4805		
x	1301	DAMAGED	OK		OK	OK	HAZ MISSING	IMG4806		
BI210	1300	DAMAGED	NEED CLEAN	NO	OK	OK	OK	IMG4807		
BI168	1311	OK	OK		OK	OK	OK	IMG4808		
BI209	1300	OK	OK		OK	OK	SUBSTITUTE	IMG4809		

82	82	9	42	20			39		12
			51%	24%			48%		
	MISSING	0	0	0			0		
	DAMAGED	9	16	0			0		
	NO	0	0	20			0		
	SUBSTITUTE	0	0	0			30		
	HAZ MISSING	0	0	0			9		
	NEED CLEAN	0	26	0			0		
									17

N PETERS STREET		JORGENSEN SURVEY 02152022							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
PR73	101	DAMAGED	DAMAGED	3	OK	OK	OK	IMG4853	
x	100	OK	OK	2LED	OK	OK	OK	IMG4854	
x	100	OK	OK	2LED	OK	OK	OK	IMG4855	
x	100	OK	OK	2LED	OK	OK	OK	IMG4856	
x	100	OK	OK	2LED	OK	OK	OK	IMG4857	
x	101	OK	OK	2LED	OK	OK	OK	IMG4858	
PR524	200	OK	DAMAGED	2	OK	OK	HAZ MISSING	IMG4859	
PR523	201	OK	NEED CLEAN	1	PAINT	PAINT	SUBSTITUTE	IMG4860	
PR525	200	OK	0	2	OK	OK	OK	IMG4861	
PR526	230	OK	NEED CLEAN	2	OK	OK	HAZ MISSING	IMG4862	
AV442	301	OK	OK	1 LED	OK	OK	OK	IMG4863	
AV443	320	OK	NEED CLEAN	2	OK	OK	OK	IMG4864	
AV444	330	OK	NEED CLEAN	2	OK	OK	OK	IMG4865	
AV445	340	OK	NEED CLEAN	2	OK	OK	OK	IMG4866	
AV446	406	OK	OK		PAINT	PAINT	OK		
O1	401	OK	OK		OK	OK	OK	IMG4867	
BIH205	409	DAMAGED	OK		OK	OK	OK		
AU447	406	OK	OK	2	PAINT	PAINT	HAZ MISSING		
AV448	414	OK	OK	2	PAINT	PAINT	HAZ MISSING	IMG4868	
19	19	2	7	0			4		0
			37%	0%			21%		
	MISSING	0	0	0			0		
	DAMAGED	2	2	0			0		
	NO	0	0	0			0		
	SUBSTITUTE	0	0	0			0		
	HAZ MISSING	0	0	0			4		
	NEED CLEAN	0	5	0			0		



100

EXCHANGE ALLY		JORGENSEN SURVEY 02092022							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
PR345	110	OK	OK		OK	OK	HAZ MISSING	IMG4842	
PR346	101	DAMAGED	OK	NO	OK	OK	OK	IMG4843	2022-886468
AV260	102	OK	DAMAGED		OK	OK	OK	IMG4844	2022-886472
AV356	105	OK	OK	NO	OK	OK	OK	IMG4845	2022-886476
4	4	1	1	2			1		3
			25%	50%			25%		
	MISSING	0	0	0			0		
	DAMAGED	1	1	0			0		
	NO	0	0	2			0		
	SUBSTITUTE	0	0	0			0		
	HAZ MISSING	0	0	0			1		
	NEED CLEAN	0	0	0			0		

100

DORSIERE STREET		JORGENSEN SURVEY 02102022							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
PR79	101	DAMAGED	3 LIGHT ALL DAMAGED	NO	OK	OK	SUBSTITUTE	IMG4723	
PR539	100	OK	OK		OK	OK	SUBSTITUTE	IMG4725	
PR540	100	DAMAGED	OK		OK	OK	SUBSTITUTE	IMG4726	
PR548	120	DAMAGED	D	TEL	OK	OK	SUBSTITUTE	IMG4727	
4	4	3	0	1			4		0
			0%	25%			100%		
	MISSING	0	0	0			0		
	DAMAGED	3	0	0			0		
	NO	0	0	1			0		
	SUBSTITUTE	0	0	0			4		
	HAZ MISSING	0	0	0			0		
	NEED CLEAN	0	0	0			0		

200	CLINTON ALLY		SURVEY JORGENSEN 02152022							
	LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
	UA366	201	DAMAGED	DAMAGED		OK	OK	SUBSTITUTE		
	UA367	205	OK	OK		OK	OK	SUBSTITUTE		
	x	224	OK	OK		OK	OK	OK		
	AV360	225	DAMAGED	OK		OK	OK	SUBSTITUTE		
	4	4	2	1	0			3		0
				25%	0%			75%		
		MISSING	0	0	0			0		
		DAMAGED	2	1	0			0		
		NO	0	0	0			0		
		SUBSTITUTE	0	0	0			3		
		HAZ MISSING	0	0	0			0		
		NEED CLEAN	0	0	0			0		

FRENCH MARKET ST AND PLACE		SURVEY JORGENSEN 02232022							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
BJ 187	940 N PETERS / FM	OK	NEED CLEAN		OK	OK	SUBSTITUTE	IMG 4891	
x	940 N PETERS / FM	OK	OK		OK	OK	SUBSTITUTE	IMG 4892	
BJ 188	1008	DAMAGED	OK		OK	OK	SUBSTITUTE	IMG 4893	
x	1009			5G				IMG 4894	
BJ 189	1012	OK	NEED CLEAN		OK	OK	OK	IMG 4895	
BJ 191	1013	OK	DAMAGED		OK	OK	OK	IMG 4896	
x	1014	OK	NEED CLEAN		OK	OK	OK	IMG 4897	
BJ 192	1015	DAMAGED	OK		OK	OK	OK	IMG 4898	
x	1101	OK	OK		OK	OK	OK	IMG 4899	
ZX 117	1140	OK	OK		OK	OK	SUBSTITUTE	IMG 4900	
x	1200			NO				IMG 4901	
x	1210			NO				IMG 4902	
BJ 204	1220	OK	OK		PAINT	PAINT	HAZ MISSING	IMG 4903	
BJ 206	1211	OK	OK		PAINT	PAINT	HAZ MISSING	IMG 4904	
BJ 205	12221	OK	OK		PAINT	PAINT	OK		
x	1101 FRENCH MARKET PLACE	OK	OK		OK	OK	OK	IMG 4915	
x	1119	OK	OK		OK	OK	OK	IMG 4916	
x	1125	OK	OK		OK	OK	OK	IMG 4917	
H 448	1143	OK	OK		OK	OK	OK	IMG 4918	
x	1159	OK	OK		OK	OK	OK	IMG 4919	
BIH 445	1167	OK	OK		OK	OK	OK	IMG 4920	
BIH 444	1191	OK	OK		OK	OK	OK	IMG 4921	
22	22	2	4	2			6		0
			18%	9%			27%		
	MISSING	0	0	0			0		
	DAMAGED	2	1	0			0		
	NO	0	0	2			0		
	SUBSTITUTE	0	0	0			4		
	HAZ MISSING	0	0	0			2		
	NEED CLEAN	0	3	0			0		

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

IBERVILLE STREET		SURVEY								311 SUBMITTAL
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO		
BR556	101	MISSING	MISSING	NO	OK	OK	SUBSTITUTE	IMG9870		2022-913754
PR558	100	OK	OK	YES	OK	OK	OK	IMG9871		
PR557	110	OK	CLEAN	YES	OK	OK	SUBSTITUTE	IMG9872		
PR555	130	DAMAGED	OK	NO	PAINT	PAINT	SUBSTITUTE	IMG9873		2022-913759
PR554	131	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9874		
PR553	140	DAMAGED	OK	NO	OK	OK	SUBSTITUTE	IMG9875		2022-913765
PR551	151	DAMAGED	OK	NO	OK	OK	SUBSTITUTE	IMG9876		2022-913767
PR552	150	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9877		
PR550	160	OK	OK	YES	OK	OK	OK	IMG9878		
PR523	401	DAMAGED	WATER IN LENSE	YES	PAINT	PAINT	SUBSTITUTE	IMG9879		
AV330	411	OK	DAMAGED	YES	OK	OK	OK	IMG9880		
UA366	413	OK	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG9881		2022-913775
UA368	423	OK	DAMAGED	YES	OK	OK	OK	IMG9882		
PR548	508	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9883		
PR547	519	OK	DAMAGED	YES	OK	OK	OK	IMG9884		
BIH200	529	OK	OK	YES	OK	OK	OK	IMG9885		
AV357	606	OK	DAMAGED	NO	OK	OK	HAZ MISSING	IMG9887		2022-913779
AV356	609	OK	OK	YES	OK	OK	OK	IMG9888		
AV355	649	OK	OK	NO	OK	OK	OK	IMG9889		2022-913783
AV215	134 ROYAL	OK	OK	YES	OK	OK	OK	IMG9890		
AV214	201 ROYAL	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9891		
AV254	710	OK	DAMAGED	YES	OK	OK	SUBSTITUTE	IMG9892		
AV253	721	OK	CLEAN	YES	OK	OK	SUBSTITUTE	IMG9893		
AV531	733	OK	CLEAN	YES	OK	OK		IMG9894		
AV350	810	DAMAGED	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG9895		2022-913793
AV349	821	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9896		
AV347	831	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9897		
AV174	201 DAUPHINE	OK	OK	NO	OK	OK	OK	IMG9898		2022-913796
AV346	901	OK	DAMAGED	YES	OK	OK	OK	IMG9899		
AV345	939	OK	DAMAGED	NO	OK	OK	OK	IMG9900		2022-913800
AV344	941	BLUE?	OK	YES	OK	OK	OK	IMG9901		
AV343	943	OK	OK	YES	OK	OK	OK	IMG9902		
AV341	1001	OK	OK	YES	OK	OK	SUBSTITUTE	IMG9903		
AV340	1015	OK	OK	YES	OK	OK	OK	IMG9904		
AV339	1030	DAMAGED	DAMAGED	NO	PAINT	PAINT	HAZ MISSING	IMG9905		2022-913810
AV338	1031	MISSING	MISSING	NO	MISSING	MISSING	MISSING	MISSING		
36	36	8	12	12			20			11
			33%	33%			56%			
	MISSING	2	2	0			1			
	DAMAGED	6	10	0			0			
	NO	0	0	12			0			
	SUBSTITUTE	0	0	0			17			
	HAZ MISSING	0	0	0			2			
	NEED CLEAN	0	0	0			0			

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

8/1/2022 0:00

BIENVILLE STREET		SURVEY							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
PR571	200	X	DAMAGED	YES	OK	OK	OK	IMG5156	
PR570	200	X	OK	YES	OK	OK	OK	IMG5157	
PR569	200	X	OK	YES	OK	OK	SUBSTITUTE	IMG5158	
PR568	208	X	OK	YES	OK	OK	SUBSTITUTE	IMG5159	
PR572									
PR567									
PR566	210	X	OK	YES	OK	OK	OK	IMG5160	
PR565	215	X	DAMAGED	NO	OK	OK	HAZ MISSING	IMG5161	2022-914786
PR563	220	X	OK	YES	OK	OK	HAZ MISSING	IMG5162	
PR564	225	X	DAMAGED	NO	OK	OK	SUBSTITUTE	IMG5163	2022-914788
AV442	245	X	OK	-	OK	OK	OK	IMG5164	
BIH442	411	DAMAGED	OK	NO	OK	OK	OK	IMG5165	2022-914789
AV360	420	OK	NEED CLEAN	YES	OK	OK	SUBSTITUTE	IMG5166	
AV336	433	OK	OK	-	BENT	OK	OK	IMG5167	
AV335	440	OK	OK	YES	OK	OK	HAZ MISSING	IMG5168	
AV362	517	OK	OK	YES	OK	OK	SUBSTITUTE	IMG5169	
AV361	536	OK	OK	YES	OK	OK	SUBSTITUTE	IMG5170	
AV363	539	OK	OK	YES	OK	OK	HAZ MISSING	IMG5171	
AV364									
AV267									
AV266									
AV365				5G					
AV366	617	OK	OK	YES	OK	OK	OK	IMG5172	
AV367	623	DAMAGED	MISSING	NO	MISSING	DAMAGED	SUBSTITUTE	IMG5173	2022-914792
AV368	625	OK	OK	YES	BENT	OK	SUBSTITUTE	IMG5174	
AV209	630	OK	DAMAGED	-	OK	OK	SUBSTITUTE	IMG5175	
AV208									
AV370									
AV369	705	MISSING	MISSING	NO	OK	OK	SUBSTITUTE	IMG5176	2022-914793
UA838	712	OK	OK	YES	OK	OK	OK	IMG5177	
AV371	777	OK	OK		OK	OK	SUBSTITUTE	IMG5178	
AV372									
AV230	780	OK	OK		OK	OK	OK	IMG5179	
AV231	801	OK	DAMAGED	YES	OK	OK	SUBSTITUTE	IMG5180	
AV373	808	OK	OK	YES	OK	OK	OK	IMG5181	
AV374	813	OK	CLEAN	YES	OK	OK	OK	IMG5182	
AV375	810	OK	OK	NO	BENT	OK	OK	IMG5183	2022-914798
AV376	815	OK	OK	YES	OK	OK	SUBSTITUTE	IMG5184	
AV169	830	MISSING	DAMAGED	NO	BENT	OK	SUBSTITUTE	IMG5185	2022-914800
AV168	900	MISSING	MISSING	NO	MISSING	DAMAGED	MISSING	IMG5186	2022-914806
AV455								IMG5187	
AV377	918	OK	OK	YES	OK	OK	OK	IMG5188	
AV378	925	OK	OK	NO	OK	OK	SUBSTITUTE	IMG5189	2022-914809
AV379	930	OK	OK	YES	OK	OK	SUBSTITUTE		
AV136				5G					
AV380	1000	OK	OK	YES	OK	OK	OK	IMG5190	
AV381	1025	OK	OK	YES	OK	OK	SUBSTITUTE	IMG5191	
AV382	1026	OK	OK	YES	OK	OK	OK	IMG5192	
AV383	1040	OK	DAMAGED LENS		PAINT REPAIR	OK	SUBSTITUTE	IMG5193	

49	38	5	10	9			23		9
			26%	24%			61%		
	MISSING	3	3	0			1		
	DAMAGED	2	6	0			0		
	NO	0	0	9			0		
	SUBSTITUTE	0	0	0			18		
	HAZ MISSING	0	0	0			4		
	NEED CLEAN	0	1	0			0		

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

CONTI STREET		SURVEY							311 SUBMITTAL
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	
AV411									
UA837	100	OK	OK	YES	OK	OK	HAZ MISSING		
AV454	111	OK	OK	YES	OK	OK	SUBSTITUTE		
AV453	115	OK	OK	YES	OK	OK	SUBSTITUTE		
AV452	120	OK	OK	YES	OK	OK	SUBSTITUTE		
AV455	200	OK	OK	YES	OK	OK	HAZ MISSING		
AV662									
AV661	205	OK	OK	YES	OK	OK	OK		
AV412									
AV411									
AV410									
AV409	525	OK	OK	NO	OK	OK	OK		2022-914939
AV408	535	OK	OK	NO	OK	OK	SUBSTITUTE		2022-914940
AV407	535	OK	OK	NO	OK	OK	OK		2022-914941
AV406	535	OK	OK	YES	OK	OK	SUBSTITUTE		
AV405	520	MISSING	MISSING	NO	OK	OK	OK		2022-914945
AV404	606	OK	OK	NO	OK	OK	OK		2022-914947
AV403	620	DAMAGED	DAMAGED	NO	OK	OK	OK		2022-914949
AV402	620	OK	DAMAGED	NO	OK	OK	OK		2022-914951
UA836	620	OK	DAMAGED	NO	OK	OK	OK		2022-914952
AV401	620	OK	OK	NO	OK	OK	OK		2022-914953
AV202									
AV400									
AV399	707	OK	DAMAGED	YES	OK	OK	SUBSTITUTE		
AV398									
AV397									
AV237									
AV211	707	OK	DAMAGED	NO	OK	OK	HAZ MISSING		2022-914955 /56
AE397	737	OK	OK	YES	OK	OK	SUBSTITUTE		
AV237									
AV238									
UA835	807	OK	OK	YES	OK	OK	SUBSTITUTE		
AV396	806	OK	OK	YES	OK	OK	SUBSTITUTE		
AV395	811	OK	OK	YES	OK	OK	OK		
AV394	814	DAMAGED	DAMAGED	NO	OK	OK	SUBSTITUTE		2022-914960
AV393	839	OK	OK	YES	OK	OK	OK		
AV392	920	OK	OK	YES	OK	OK	OK		
UA834	915	OK	OK	YES	OK	OK	OK		
AV391	923		OK	YES	OK	OK	SUBSTITUTE		
AV390	928	OK	OK	YES	OK	OK	OK		
AV141									
AV142									
AV389	945	OK	OK	NO	OK	OK	SUBSTITUTE		2022-914967
AV388	1003	OK	OK	YES	OK	OK	OK		
AV387	1010	OK	OK	YES	OK	OK	OK		
AV386	1019	OK	OK	YES	PAINT	PAINT	OK		
AV385	1026	OK	DAMAGED	YES	OK	OK	OK		
47	33	3	8	12			15		12
			24%	36%			45%		
	MISSING	1	1	0			0		
	DAMAGED	2	7	0			0		
	NO	0	0	12			0		
	SUBSTITUTE	0	0	0			12		
	HAZ MISSING	0	0	0			3		
	NEED CLEAN	0	0	0			0		

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

ST ANN STREET		SURVEY							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
UA 382	501	OK	OK	YES	OK	OK	SUBSTITUTE		
UA 383	501	OK	OK	YES	OK	OK	SUBSTITUTE		
M133									
SCC106	515	OK	OK	YES	OK	OK	OK		
SCC107	515	OK	OK	NO	OK	OK	OK		2022-922209
SCC108-1	515	OK	OK	NO	OK	OK	HAZ MISSING		2022-922216
AE51	515	OK	OK	NO	OK	OK	HAZ MISSING		2022-922219
MI 12									
MI 11									
MI 10									
MI 9									
SCC 109	529	OK	OK	NO	OK	OK	HAZ MISSING		2022-922224
AE 50	529	OK	OK	NO	OK	OK	HAZ MISSING		2022-922225
SCC110-1	529	OK	OK	NO	OK	OK	OK		2022-922227
SCC111-1	529	OK	OK	NO	OK	OK	HAZ MISSING		2022-922228
AE43	630	OK	OK	YES	OK	OK	OK		
AU494	630	OK	OK	YES	OK	OK	OK		
ZX115	627	OK	OK	YES	OK	OK	SUBSTITUTE		
ZX112	630	OK	OK	YES	OK	OK	SUBSTITUTE		
AE47	633	OK	OK	YES	OK	OK	SUBSTITUTE		
AE133									
AE134	706	OK	OK	YES	OK	OK	OK		
AQ136	713	OK	OK	YES	OK	OK	OK		
AQ132	723	OK	OK	YES	OK	OK	OK		
AQ131	723	OK	OK	YES	OK	OK	SUBSTITUTE		
AQ130	737	OK	OK	YES	OK	OK	OK		
AQ39									
AQ37									
AQ129									
AQ128	815	OK	DAMAGED	NO	OK	OK	HAZ MISSING		2022-922248
AQ127	820	OK	OK	NO	OK	OK	OK		2022-922250
AQ126	833	OK	OK	YES	OK	OK	OK		
AQ66									
AQ67									
AQ125	910			5G					
AQ124	917	OK	OK	YES	OK	OK	SUBSTITUTE		
AQ123	928	OK	OK	YES	OK		OK		
AQ122									
AQ91									
AQ90 / BIH217	1000	OK	OK	YES	OK	OK	OK		
AQ121	1019	OK	OK	YES	OK	OK	OK		
AQ120	1024	OK	OK	YES	OK	OK	OK		

42	29	0	1	9			13		9
			3%	31%			45%		
	MISSING	0	0	0	0	0	0		
	DAMAGED	0	1	0	0	0	0		
	NO	0	0	9	0	0	0		
	SUBSTITUTE	0	0	0	0	0	7		
	HAZ MISSING	0	0	0	0	0	6		

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

MADISON AVE		SURVEY - MADDIE							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
MISSING ID #	508 MADISON (ON 311 ASSET MAP)	OK	NEED CLEAN	NO	OK	RUST	OK		
BIH249	818 CHARTRES	MISSING	DAMAGED	OK	RUST	RUST	HAZ MISSING		
UA484	823 DECATUR	MISSING	DAMAGED	NO	RUST	RUST	DAMAGED		2022-926306
UA487	509 MADISON	OK	NEED CLEAN	OK	OK	DAMAGED	SUBSTITUE		
UA486	525 MADISON	OK	DAMAGED	OK	OK	OK	OK		
AE54	538 MADISON	OK	DAMAGED	OK	RUST	RUST	OK		
AE55	541 MADISON	OK	DAMAGED	OK	PAINT	DAMAGED	HAZ MISSING		
7	7	2	7	2			3		1
			100%	29%			43%		
	MISSING	2	0	0			0		
	DAMAGED	0	5	0			1		
	NO	0	0	2			0		
	SUBSTITUTE	0	0	0			0		
	HAZ MISSING	0	0	0			2		
	NEED CLEAN	0	2	0			0		

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

ST PHILLIPS STREET		SURVEY							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
BJ67	512	DAMAGED	OK	YES	OK	OK	SUBSTITUTE		
BJ66	533	OK	OK	YES	OK	OK	OK		
BJ65									
BJ130									
BJ131									
BJ62	620	OK	OK	YES	OK	OK	SUBSTITUTE		
BJ61	619	OK	OK	YES	OK	OK	SUBSTITUTE		
BJ60									
BJ116									
BJ117									
BJ58	700	OK	OK	YES	OK	OK	OK		
BJ57	725	OK	OK	YES	OK	OK	OK		
BJ56	730	OK	OK	NO	OK	OK	HAZ MISSING		2022-915670
BJ55	808	OK	OK	YES	OK	OK	SUBSTITUTE		
BJ77									
BJ54	817	OK	OK	YES	OK	OK	OK		
AQ108	826	OK	OK	YES	OK	OK	OK		
AQ61									
AQ107	910	OK	OK	YES	DAMAGED	OK	OK		
AQ106	923	OK	OK	YES	OK	OK	SUBSTITUTE		
AQ105									
AQ104	1014								
AQ96									
AQ97									
AQ103	1027	OK	OK	YES	OK	OK	HAZ MISSING		
AQ102									
26	14	1	0	1			7		1
			0%	7%			50%		
	MISSING	0	0	0			0		
	DAMAGED	1	0	0			0		
	NO	0	0	1			0		
	SUBSTITUTE	0	0	0			5		
	HAZ MISSING	0	0	0			2		
	NEED CLEAN	0	0	0			0		

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

[illegible]

JANE

BARRACKS STREET		SURVEY								311 SUBMITTAL
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO		
HP 22	1029	OK	OK	OK	OK	OK	OK			
Hhp 21	1000	OK	OK	OK	OK	OK	OK			
BIH 229	1019	OK	OK	OK	OK	OK	OK			
HP 18	1005	OK	OK	NO	OK	OK	OK		2022-902141	
HP 17	1300 BURGUNDY	OK	OK	NO	OK	OK	OK		2022-902150	
HP 16	930 CABRINI PARK	DAMAGED	OK	OK	OK	OK	OK			
HP 15	923	OK	OK	OK	OK	OK	OK			
YC 11										
BJ 2										
BJ 1										
BJ 53	832	OK	DAMAGED	OK	OK	OK	OK			
BJ 52	821	OK	OK	OK	OK	OK	OK			
BJ 51	802	OK	OK	OK	OK	OK	OK			
BJ 94										
BJ 50	734	OK	OK	OK	OK	OK	OK			
BJ 49	721	OK	DAMAGED	OK	OK	OK	OK			
BJ 48	710	OK	OK	OK	OK	OK	OK			
BJ 100										
BJ 99										
BJ 47										
BJ 46	623	OK	OK	OK	OK	OK	OK			
BJ 45	604	OK	OK	OK	OK	OK	OK			
BJ 141										
BJ 142										
BJ 44	538	OK	NEED CLEAN	OK	OK	OK	DAMAGED			
BJ 43										
BJ 42	508	OK	OK	NO	OK	OK	OK		2022-902195	
BJ 169	505	OK	OK	OK	OK	OK	HAZ MISSING			
UA 266F										
BJ 41	433 (MINT)	OK	OK	OK	OK	OK	OK			
BJ 40	424	OK	OK	OK	OK	OK	OK			
BJ 39	419 (MINT)	OK	OK	OK	OK	OK	OK			
BJ 38										
BJ 37	97 French market place (MINT)	DAMAGED	OK	OK	OK	OK	OK			
BJ 36	98 French market place (MINT)	OK	OK	OK	OK	OK	OK			
35	23	2	3	3			2		3	
			13%	13%			9%			
	MISSING	0	0	0			0			
	DAMAGED	2	2	0			1			
	NO	0	0	3			0			
	SUBSTITUTE	0	0	0			0			
	HAZ MISSING	0	0	0			1			
	NEED CLEAN	0	1	0			0			

PRINT LANDSCAPE ON 8X11 PAPER TO RECORD WALKING SURVEY

ESPLANADE STREET		SURVEY							
LIGHT ID	CLOSEST ADDRESS	SENSOR	LIGHT & LENS	FUNCTION	UPPER POST	BASE	COVER	PHOTO	311 SUBMITTAL
FQ SIDE OF STREET									
BJ205									
BJ148	400	OK	OK	YES	OK	OK	OK		
BJ47	400	OK	OK	YES	OK	OK	SUBSTITUTE		
BJ146	400	OK	OK	YES	OK	OK	OK		
BJ145	510	OK	OK	YES	OK	OK	OK		
BJ144	534	OK	OK	YES	OK	OK	OK		
BJ167	600	OK	OK	YES	OK	OK	OK		
BJ166	628	OK	OK	YES	OK	OK	SUBSTITUTE		
BJ165	640	OK	OK	YES	OK	OK	OK		
BJ164	714	OK	OK	YES	DAMAGED	OK	OK		
BJ163	730	OK	OK	YES	OK	OK	OK		
BJ162	806	OK	OK	YES	OK	OK	HAZ MISSING		
BJ161	820	OK	OK	YES	OK	OK	SUBSTITUTE		
HP7	838	OK	OK	YES	OK	OK	OK		
HP6	908	OK	OK	YES	OK	OK	SUBSTITUTE		
HP5	932	OK	OK	YES	OK	OK	OK		
UA232									
HP3	1020	OK	OK	YES	OK	OK	OK		
HP2	1036	OK	OK	YES	OK	OK	OK		
MARIGNY SIDE OF STREET									
BJ149	401	OK	OK	NO	OK	OK	OK		2022-922424
BJ150	401	OK	OK	YES	OK	OK	OK		
AU35									
AU34									
V51									
BJ151	429	OK	OK	YES	OK	OK	OK		
UA165									
UA166									
BJ152	501	OK	OK	YES	OK	OK	OK		
UA167									
UA168									
BJ153	529	OK	OK	YES	OK	OK	OK		
UA170									
BJ154	547	OK	OK	YES	OK	OK	OK		
UA171									
BJ155	617	OK	OK	YES	OK	OK	OK		
UA172									
UA173									
BJ156	635	OK	OK	YES	OK	OK	OK		
UA174									
BJ157	713	OK	OK	YES	OK	OK	OK		
UA175									
UA269									
BJ158									
UA270									
UA271									
BJ159	741	OK	OK	YES	OK	OK	OK		
BJ160	815	OK	OK	YES	OK	OK	OK		
UA272									
YC48									
HP8	837	OK	OK	NO	OK	OK	H		2022-922435
YC74									
HP9	905	OK	OK	YES	DAMAGED	OK	OK		
YC75									
HP10	919	OK	OK	YES	OK	OK	OK		
YC76									
HP4									
HP11	937	OK	OK	YES	OK	OK	OK		
YC77									
HP12	1009	DAMAGED	OK	NO	OK	OK	OK		2022-922438
YC78									
HP13	1029	OK	OK	YES	OK	OK	S		
YC79									

64	34	1	0	3			5		3
			0%	9%			15%		
	MISSING	0	0	0			0		
	DAMAGED	1	0	0			0		
	NO	0	0	3			0		
	SUBSTITUTE	0	0	0			4		
	HAZ MISSING	0	0	0			1		
	NEED CLEAN	0	0	0			0		